

General Environmental Incident Summary

Incident: 2115 **Date/Time Notice:** 11/15/2013 1523 **DEM Incident No:**
Responsible Party: Bridger Transportation, LLC
Date Incident: 11/15/2013 **Time Incident:** 1000 **Duration:** 10 minutes
County: Mountrail **Twp:** 153 **Rng:** 92 **Sec:** 25 **Qtr:**
Lat: 48.05077 **Long:** -102.41300 **Method:** Navigation quality GPS
Location Description: Whiting Oil and Gas, Derry State 11-25 location,

Submitted By: David LaMay **Affiliation:** Employee
Address: 800 Spring Street, Suite 205
City: Shreveport **State:** LA **Zip:** 71101

Received By:

Contact Person: Otis Randle
15510 Wright Brothers Dr.
Addison, TX 75001

Distance Nearest Occupied Building:

Type of Incident: valve leak at loading pot

Description of Released Contaminant: Crude Oil

Volume Spilled: 5.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Oil was released from the line once the driver disconnected his hose and drove away leaving the valve open at the loading pot.

Risk Evaluation:

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

All impacted soil will be excavated and no contaminants will remain on site. Not likely to impact any waters.

Action Taken or Planned:

The oil was initially contained in the secondary containment area surrounding the tanks. United States Environmental Services was contacted and responded immediately to the incident to begin clean up. They began digging out all stained and contaminated soil and will backfill the area with clean soil.

Wastes Disposal Location: All waste will be disposed of at Prairie Disposal Facility.

Agencies Involved:

Updates

Date: 11/20/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Release occurred on an oil well location. The release was contained on location. NDIC Oil and Gas Division has responsibility for cleanup oversight.